

D.R.T.K. SHKODËR

MIRATOHET
Sekretari I KKTKM
Joli Mitrojorgji

PREVENTIV

Objekti : Projekt restaurimi "OBJEKTIT MUZEU KOMBETAR I FOTOGRAFISE MARUBI"

Nr	Nr. Analiz	Emertimi	Njesia	Sasia	JAVA 1	JAVA 2	JAVA 3	JAVA 4	JAVA 5
1	R.IV.5	Prishje mur tulle me pastrim	m ³	2.9562					
2	R.IV.20	Çmontim dyer dritare	m ²	2.25					
3	R.V.9	Mur me tulla të lehtësuara dopio - 3m, llaç gelqere 1:3	m ²	2.25					
4	R.XI.2	Suva brenda mur tulle me krah, llaç gëlqere 1:2	m ²	81.106					
5	2.297/b	Tavan I varur me pllka gipsi 60x60cm	m ²	29.7					
6	2.267/1	Shtrese me pllaka porcelanat	m ²	3.85					
7	2.485/g	F.V priza shuko brenda murit 2 fazore 25 A	cope	7					
8	2.485/b	F.V priza bivalente 220V 10A 2P-T	cope	7					
9	2.485/1	F.V Çeles 1 polar 220V 10A	cope	6					
10	2.480/2	F.V tub plastmasi Ø 18 ~ 21 mm	ml	20					
11	480/3	F.V tub plastmasi Ø 22 ~ 26 mm	ml	20					
12	480/5	F.V tub plastmasi Ø 31 ~ 36 mm	ml	20					
13	2.481/1	F.V percjelles PV-500 Ø 1.5 mm2	ml	20					
14	2.481/2	F.V percjelles PV-500 Ø 2.5 mm2	ml	20					
15	2.481/3	F.V percjelles PV-500 Ø 4 mm2	ml	20					
16	2.471	F.V. Ndricues fluoreshent 4x18w,IP40 fluoreshent 4x18w,IP40	cope	20					
17	An	Sistemi I kondicionimit							

Punoi:
Sabrina Kuçi

Drejtore
Amila Gjyzezi

Miratohet
Pergj.Sektore.Petrit Bilali